

Keyboard Shortcuts and Mouse Controls

File Management

To do this	Press
New model	Ctrl + N
Open	Ctrl + O
Import	Ctrl + I
Save	Ctrl + S
Save as	Ctrl + Shift + S

Workspace

To do this	Press
Open context sensitive help	F1
Search tool	Ctrl + F

View

To do this	Press
Rotate	Middle Mouse Drag Arrow Keys
Set rotation center	Ctrl + Middle Mouse Click on model
Reset rotation center	Ctrl + Middle Mouse Click in space
Pan	Right Mouse Drag Left + Right Mouse Drag

To do this	Press
Zoom	Middle Mouse Scroll
Circle zoom	Alt + Middle Mouse Draw Z, then Left Mouse Draw
Fit (and fit selected)	F
Go back to previous view	B
Save a view	Ctrl + Numeric Key (0-9)
Recall a view	Numeric Key (0-9)

Display

To do this	Press
Show all of the current entity type	A
Hide selection	H
Isolate selection	I
Reverse display	R
Show adjacent entities to selection	J

Editing


To do this	Press
Delete	Delete
Undo	Ctrl + Z
Redo	Ctrl + Y
Perform an action This is akin to clicking Apply on a guide bar.	Middle Mouse Click

Selection

To do this	Press
Window select	Left Mouse Drag
Append selection	Ctrl + Left Mouse Click
Deselect	Shift + Left Mouse Click
Select displayed	Ctrl + A
Select all	Ctrl + Shift + A
Select adjacent	Ctrl + J
Select attached	Ctrl + T
Select similar (based on type and config if applicable)	Ctrl + M
Reverse selection	Ctrl + R
Quick advanced selection Configurable via Mouse Control Preferences	Alt + Left Mouse Click
Adjust feature angle when selecting elements By Face or By Edge	Alt + Scroll
Suspend snaps	Alt
Clear selection	Esc

Entity Selector

To do this	Press
Set to lines	L
Set to points/parts	P
Set to solids/surfaces/systems	S

 **Tip:** For entity types that have the same first letter (solids, surfaces), continually press the keyboard shortcut to alternate between entity types.

Browser

To do this	Press
Show selection	A
Hide selection	H
Isolate selection	I
Delete	Delete
Edit (Post Browser only)	E

Common Across Tools

To do this	Press
Cycle through secondary ribbon tools	Ctrl + Tab
Cycle through guide bar selectors	Tab
Exit a tool	Esc Right-click and mouse through the exit control Double right-click